

NEW FEATURES

This is a service pack release for FieldGenius to add support for new survey instruments and fix high priority defects.

NEW AND UPDATED INSTRUMENT DRIVERS

GNSS

- Topcon HiperII - Add new driver.
- Topcon HiperV - Add new driver.
- Leica - Remove Leica 1100 driver no longer supported device.

Coordinate Systems

- No new coordinate system updates.

DEFECTS FIXED

- FOIF FieldGenius – Fixed issue so the Observation Toolbar shows red.
- ComNav – Fixed Bluetooth connect issue with Windows 10.
- Automap – Fixed window goes full screen no matter the windows settings issue.
- Station / Offset, Ground to Grid scale factor – Fixed issue that the scale factor was not being applied.
- Traverse Report – Fixed issue with the adjustments not being applied to the database.

KNOWN ISSUES

Disto S910 - First photo taken with project can provide an error, additional photos are taken and stored fine.

Photo Notes – Camera rotation is not supported.

LandXML – LandXML alignments containing a sequence of Spiral-Curve-Spiral-Curve-Spiral are not properly displayed.

Multiset Structured – Angle only backsight is not available.