

MicroSurvey FieldGenius release 10.2.30.5 adds in a new feature and specific driver improvements that were time critical for some customers. MicroSurvey has chosen to apply the limited updates to the current 10.2.30 release and increase the release version to 10.2.30.5.

## NEW FEATURES

**GroupCode - MultiLine support** – Assign a multiple lines and codes to a single measurement.

## NEW AND UPDATED INSTRUMENT DRIVERS

### GNSS

- **CHC** – New Drivers i70 and i50
- **Kolida** – New Driver K10.

### Total Station

## DEFECTS FIXED

- **Leica TS07/TS10** – Fixed issue with Observation toolbar updating location and guide light setting.

## KNOWN ISSUES

**Disto S910** - First photo taken with project can provide an error, additional photos are taken and stored fine.

**Photo Notes** – Camera rotation is not supported.

**LandXML** – LandXML alignments containing a sequence of Spiral-Curve-Spiral-Curve-Spiral are not properly displayed.

**Multiset Structured** – Angle only backsight is not available.

## NEW FEATURE AND DRIVER DETAILS

None.