

NEW FEATURES

- Observation Toolbar – Added persist state when switching to staking mode.

NEW AND UPDATED INSTRUMENT DRIVERS

GNSS

- CY F100 – Added New Driver.
- Hemisphere S631 GNSS - Added New Driver.
- Tersus GNSS Devices – Updated reference distance for GNSS.
- GENEQ F100 – Updated Driver.
- Leica Devices - Add support for Satel 900MHz Radio.
- Tersus - Add support for GSA and GSV messages.
- Stonex - Add S990A and S980 - Added New Driver.
- KOLIDA K1PRO and K20s - Added New Drivers.
- CHC i80 – Updated driver to support new firmware version.

Total Station

- CHC CTS-112R4 - Added New Driver.

Coordinate Systems

- POSGAR 94 and 2007 for Argentina

DEFECTS FIXED

- Observation Toolbar – Fixed bug when switching to staking mode.
- Changing GNSS Tolerance – Fixed wait dialog does not close issue.
- eSurvey E100 – Updated driver to address GSM issue.

KNOWN ISSUES

Disto S910 - First photo taken with project can provide an error, additional photos are taken and stored fine.

Photo Notes – Camera rotation is not supported.

LandXML – LandXML alignments containing a sequence of Spiral-Curve-Spiral-Curve-Spiral are not properly displayed.

Multiset Structured – Angle only backsight is not available.