

NEW FEATURES

None for this Release

NEW AND UPDATED INSTRUMENT DRIVERS

GNSS

- **CHC** – Update i80 driver with new SDK
- **Tersus** – Added new driver for Oscar
- **South** – Updated GNSS drivers to correspond with latest firmware updates
- **Ruide** – Added COMET R8i driver
- **DT Research** – Added built-in antenna offsets for Hemisphere
- **DT Research** – Added built-in antenna offsets for S100
- **Stonex** – Added NTRIP server support
- **Kolida** – New Driver K5

Coordinate Systems

- **Netherlands** – Added RDNAP 2018 support
- **China** – Added Chinese Coordinate System

DEFECTS FIXED

- **South** – Fixed issue resulting from firmware change
- **MDOT CutSheet Report** – Fixed issue where Cut/Fill & Standard Deviation columns were incorrectly filled.
- **Tersus** – Fixed Oscar NTRIP issues

KNOWN ISSUES

Disto S910 - First photo taken with project can provide an error, additional photos are taken and stored fine.

Photo Notes – Camera rotation is not supported.

LandXML – LandXML alignments containing a sequence of Spiral-Curve-Spiral-Curve-Spiral are not properly displayed.

Multiset Structured – Angle only backsight is not available.

NEW FEATURE AND DRIVER DETAILS

None.