

NEW FEATURES

This is a hot-patch service pack release of new GNSS drivers and defect fixes. No new features added.

NEW AND UPDATED INSTRUMENT DRIVERS

GNSS

- Tersus - Added additional features to Oscar driver.
- Leica - Update data collector internet Bluetooth connection.
- Bince - Add N90 GNSS driver.
- Leica - Add driver for GS16L.

Coordinate Systems

- No new Coordinate systems added

DEFECTS FIXED

- GeoMax Zoom 80 – Fixed ATR not working issue.
- GeoMax Zoom 90 – Fixed issue with live staking freeze when TRK enabled.
- Sokkia - iX, - Fixed issue with being able to continue after selecting an invalid target in target manager.
- Fixed error in the staked difference value stored in the raw file when the tracking option is turned on.

KNOWN ISSUES

Disto S910 - First photo taken with project can provide an error, additional photos are taken and stored fine.

Photo Notes – Camera rotation is not supported.

LandXML – LandXML alignments containing a sequence of Spiral-Curve-Spiral-Curve-Spiral are not properly displayed.

Multiset Structured – Angle only backsight is not available.

NEW FEATURE AND DRIVER DETAILS

None.