



## NEW FEATURES

This is a hot-patch service pack release of new GNSS drivers and defect fixes. No new features added.

## NEW AND UPDATED INSTRUMENT DRIVERS

### GNSS

- Tersus - Add additional features to Oscar driver.
- Leica - Update data collector internet connection.
- Bince - Add N90 GNSS driver.
- Leica - Add driver for GS16L.

### Coordinate Systems

No new Coordinate systems added

## DEFECTS FIXED

- GeoMax Zoom 80 – Fixed ATR not working issue.
- GeoMax Zoom 90 – Fixed issue with live staking freeze when TRK enabled.
- Sokkia - iX, - Fixed issue with being able to continue after selecting an invalid target in target manager.
- Fixed error in the staked difference value stored in the raw file when tracking option is turned on.

## KNOWN ISSUES

**Disto S910** - First photo taken with project can provide an error, additional photos are taken and stored fine.

**Photo Notes** – Camera rotation is not supported.

**LandXML** – LandXML alignments containing a sequence of Spiral-Curve-Spiral-Curve-Spiral are not properly displayed.

**Multiset Structured** – Angle only backsight is not available.

## NEW FEATURES AND DRIVER DETAILS

None.