

NEW FEATURES

- **AP20 Support** – Added support for Auto Pole available for Leica Total Stations
- **Depth sounder Export** – Updated exports to include depth sounder export

NEW AND UPDATED INSTRUMENT DRIVERS

GNSS

- **Hemisphere S631** – Support for BDS constellations

Total Station

- **South NTS New** – added new driver

COORDINATE SYSTEMS

- **SLOVRP2016** – new geoid model for Slovenia
- **Local Grid Mauritius 2012** – added new coordinate system

DEFECTS FIXED

- **Deleting multiple points** – Addressed with deleting multiple points not deleting full selection
- **GNSS Offset Measurement** – addressed issue with height computation not applying localization parameters

KNOWN ISSUES

- **Disto S910** - First photo taken with project can provide an error, additional photos are taken and stored fine.
- **Photo Notes** – Camera rotation is not supported.
- **LandXML** – LandXML alignments containing a sequence of Spiral-Curve-Spiral-Curve-Spiral are not properly displayed.
- **Multiset Structured** – Angle only backsight is not available.