



0 5 10 15 20 25

- Exhibit #1 = Running Shoe and Glasses
- Exhibit #2 = Black Plastic
- Exhibit #3 = Orange Plastic
- Exhibit #4 = Curb Stikes
- Exhibit #5 = Clear Plastic
- Exhibit #6 = Tire Scuff Mark
- Exhibit #7 = Soda Cup
- Exhibit #8 = Tire Scuff Mark
- Exhibit #9 = POI with V2
- Exhibit #10 = V2 Tire Mark









- [Faint header text, possibly "OFFICE OF THE ATTORNEY GENERAL"]
 [Faint text, possibly "STATE OF NEW YORK"]
 [Faint text, possibly "IN SENATE"]
 [Faint text, possibly "JANUARY 1, 1900"]
 [Faint text, possibly "REPORT OF THE"]
 [Faint text, possibly "COMMISSIONER OF THE"]
 [Faint text, possibly "DEPARTMENT OF"]
 [Faint text, possibly "CORRECTIONS"]
 [Faint text, possibly "FOR THE YEAR"]
 [Faint text, possibly "1899"]
 [Faint text, possibly "ALBANY"]
 [Faint text, possibly "1900"]






- Exhibit #1 = Running Shoe and Glasses
- Exhibit #2 = Black Plastic
- Exhibit #3 = Orange Plastic
- Exhibit #4 = Curb Stikes
- Exhibit #5 = Clear Plastic
- Exhibit #6 = Tire Scuff Mark
- Exhibit #7 = Soda Cup
- Exhibit #8 = Tire Scuff Mark
- Exhibit #9 = POI with V2
- Exhibit #10 = V2 Tire Mark















Vehicle Four
Final Rest

Vehicle Five
Final Rest

Entrance

Vehicle One
Final Rest

Entrance

11.47

46.82

Tire Mark

Entrance

26th Street

6.31

Vehicle Three
Vehicle Two


Entrance


Exhibit Marker #10


10.58

Exhibit Marker #9


Mall Entrance











Estimated Path of Travel to get to the Sidewalk

12.26

Resturant Entrance

